

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 10-28-09 Time: 10 AM Location: 23175. Roane St.

Please Circle Appropriate Action: New Line Installation / Line Repair Service Line:

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date: Time of Initial Flush Length of Time of Initial Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service: YES  NO  Number of Customers Affected: 4

Main Size: 2" Repaired Under Pressure: YES  NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? YES NO

Time Water Main Valved Off (positive pressure removed): 1 pm am pm

Nature of Leak or Break

Material failure

Were State approved or AWWA Standards Followed YES NO

Detailed summary of repair procedure used (Use back of page if needed)

We cleaned pipe with Bleeth + dug 16" below main + around main + put together + back in service

Was water main contaminated during the repair process? (YES NO)

Disinfection Procedure - Calculations (Use back of page if needed)

Amount of Time Line Flushed \_\_\_\_\_ Minutes Residual \_\_\_\_\_ mg L

Ending Chlorine \_\_\_\_\_

Bacteriological Sample Collected: YES  NO

Results\*\* \_\_\_\_\_

\*\*Attach copy of results to record)

Date: Time Water Main Returned to Service: \_\_\_\_\_ am pm

Additional Comments

