

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-24-13 Time: 12:00 Location: Airport Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

**COPY**

1-25-13  
J

**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed: (YES / NO)  
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_  
Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial  
Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

**FOR LINE REPAIRS:**

Interruption of Water Service: YES \_\_\_ NO  Number of Customers Affected: 0

Main Size: 6" PVC Repaired Under Pressure: YES  NO \_\_\_

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break: vacant top leaking

Were State approved or AWWA Standards Followed: (YES / NO) NO Removed saddle + Banded  
Detailed summary of repair procedure used (Use back of page if needed):

Was water main contaminated during the repair process? (YES / NO) NO  
Disinfection Procedure / Calculations (Use back of page if needed): Bleached Bed

Amount of Time Line Flushed: \_\_\_\_\_ Minutes Ending Chlorine  
Residual: \_\_\_\_\_ mg/L

Bacteriological Sample Collected: YES \_\_\_ NO \_\_\_ Results\*\*: \_\_\_\_\_  
(\*Attach copy of results to record)

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments: See Photos

Adam - Donnie - Jimmy - James T

COPY