

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-12-10 Time: 1:00 p.m. Location: Airport Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

Date: Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size 6" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO

Time Water Main Valved Off (positive pressure removed): 12 am pm

Nature of Leak or Break: 20ft section of pipe blew out bell to bell

Were State approved or AWWA Standards Followed: (YES) NO
Detailed summary of repair procedure used (Use back of page if needed):

Replaced 20ft section with knock-on

Was water main contaminated during the repair process? (YES) (NO) Bleached
Disinfection Procedure / Calculations (Use back of page if needed): pipe & knock-on

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results:
**Attach copy of results to record)

Date: Time Water Main Returned to Service: 9-12-20 10 3:30 am pm

Additional Comments:

