

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 5-24-11 Time: 11:00 a.m. Location: Childs Rd & Martin Cir

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected: 5

Main Size: 6" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: old Killed out 2" tap out of 6" Tee w/ Plus & 2" outlet

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of repair procedure used (Use back of page if needed):
Removed valve and gate nipple from 6" tee and put in 2" Brass Plus

Was water main contaminated during the repair process? (YES (NO)) Continuous
Disinfection Procedure / Calculations (Use back of page if needed): Positive Pressure
Opened blow-off at end of Martin Hollow to set air out

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES NO Results**: _____
(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments: See Photos Adam-Billy-Bull-Reed

Rev 01-21-09
Only had 5 customers at end of Martin Hollow without water for about 10 min.

