

21

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 11-4-14 Time: 2:00 Location: Intersection of Riggs Chapel + Clifty Creek Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected: 0

Main Size: 4" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am / pm

Nature of Leak or Break: 1" split in pipe

Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):

Cleaned pipe and placed 7 1/2" band over split

Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L

Bacteriological Sample Collected: YES NO Results: (**Attach copy of results to record)

Date / Time Water Main Returned to Service: am / pm

Additional Comments: Taylor, Ronnie, Jimmy, TJ

