

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-20-10 Time: 4:30 P.M. Location: Jasper Dr.

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date - Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size 1" copper Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break: pin hole in 1" copper main

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? (YES NO)

Disinfection Procedure / Calculations (Use back of page if needed): Bleached band

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results\*\*

\*\* Attach copy of results to record)

Date - Time Water Main Returned to Service: 20 am / pm

Additional Comments:

Been leaking about a month

See Photos

