

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8/4/10 Time: 1:45 Location: 012 Saw Mill

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed: (YES / NO)  
Detailed summary of disinfection procedure used (Use back of page if needed):

Date / Time of Initial Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

**FOR LINE REPAIRS:**

Interruption of Water Service: YES \_\_\_\_\_ NO  Number of Customers Affected: 0

Main Size: 4" PVC Repaired Under Pressure: YES  NO \_\_\_\_\_

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break: Pinhole in Main

Were State approved or AWWA Standards Followed: (YES / NO) YES  
Detailed summary of repair procedure used (Use back of page if needed):  
Bleacher Band

Was water main contaminated during the repair process? (YES / NO) NO  
Disinfection Procedure / Calculations (Use back of page if needed):  
Bleacher Band and cleaned pipe before putting on Band.

Amount of Time Line Flushed: \_\_\_\_\_ Minutes Ending Chlorine Residual: \_\_\_\_\_ mg/L

Bacteriological Sample Collected: YES \_\_\_\_\_ NO \_\_\_\_\_ Results\*\*:

Date / Time Water Main Returned to Service: \_\_\_\_\_ 20 \_\_\_\_\_ am / pm

Additional Comments:

Taylor, Adam, Billy, Reed, Drew, Danie

