

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 9-30-10 Time 4:00 p.m. Location Snow Hill Rd

Please check the appropriate action: New Line Installation Line Repair Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date Time of Initial Flush Length of Time of Initial

Flush Chlorine Residual after Flush

Water supply (WS) Project Number

FOR LINE REPAIRS

Interruption of Water Service YES NO Number of Customers Affected 2

Main Size 3/4 plastic Repaired Under Pressure YES NO

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? YES

NO

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Replaced leaking plastic service

Were State approved or AWWA Standards Followed (YES NO)

Detailed summary of repair procedure used (Use back of page if needed)

Replaced split service with copper

Was water main contaminated during the repair process? (YES NO)

Disinfection Procedure Calculations (Use back of page if needed)

Flushed line

Amount of Time Line Flushed

Minutes

Ending Chlorine 7.20

Residual mg/L

Bacteriological Sample Collected YES NO

Results**

**Attach copy of results to record

Date Time Water Main Returned to Service

am pm

Additional Comments

